



FAQ

Frequently asked questions

MXL2, MXG and MXS power noise related to the “crank”



Interference

MXL2, MXG and MXS power noise related to the “crank”

Problem

Dash locks at the “crank”.

Note

This problem may appear on the following systems:

- **MXL2:** up to SN 4302188
- **MXS:** up to SN 450087
- **MXG:** up to SN 4201217

Solution

Use the external power **filter** EOF-01 part number: **X08EPF000**

