



FAQ

Frequently asked questions

Configuring a generic fuel level sensor with RS2





Configuring a generic fuel level sensor with RS2

Question:

How can I configure a generic fuel level sensor with RS2?

Answer:

Once the sensor and the additional pull up resistor connected, you need to find the correspondence between tension read by AiM device and fuel level in the tank and ensure that your AiM device reads this correspondence.

Proceed adding fuel step by step (eg. 3 litres at a time); at the same time go Online with Race Studio 2 to read the tension (mV) detected by AiM device in real time. Take note of mill volts and corresponding litres poured in the tank to complete sensor characterization.

Once all needed info collected, use Race Studio 2 **custom sensor** menu, to fill in collected values and make the software compute the sensor curve. The new sensor is now available to be set on an analog input.

Race Studio 2

Proceed as follows:

- run the software and press "Custom Sensor"
- select type of measure, measure unit, enable the rows you need and fill in collected values (1)
- press "Compute curve" (2), fill in sensor name and press "save sensor" (3)
- press "Exit" (4)

The screenshot shows the 'Customize sensor' dialog box in RaceStudio 2.55.94. The dialog is divided into several sections:

- Table:** A table with columns 'x [mV]', 'y [gal]', and 'Curve Error'. Row 1 is highlighted with a red box and a '1' callout. The data in the table is:

	x [mV]	y [gal]	Curve Error
<input checked="" type="checkbox"/>	1000	0	-0.000
<input checked="" type="checkbox"/>	5000	10	0.000
<input type="checkbox"/>	0	0	0.0
<input type="checkbox"/>	0	0	0.0
<input type="checkbox"/>	0	0	0.0
<input type="checkbox"/>	0	0	0.0
<input type="checkbox"/>	0	0	0.0
<input type="checkbox"/>	0	0	0.0
<input type="checkbox"/>	0	0	0.0
<input type="checkbox"/>	0	0	0.0
<input type="checkbox"/>	0	0	0.0
<input type="checkbox"/>	0	0	0.0
<input type="checkbox"/>	0	0	0.0
<input type="checkbox"/>	0	0	0.0
<input type="checkbox"/>	0	0	0.0
<input type="checkbox"/>	0	0	0.0
<input type="checkbox"/>	0	0	0.0
<input type="checkbox"/>	0	0	0.0
<input type="checkbox"/>	0	0	0.0
<input type="checkbox"/>	0	0	0.0
<input type="checkbox"/>	0	0	0.0
<input type="checkbox"/>	0	0	0.0
<input type="checkbox"/>	0	0	0.0
<input type="checkbox"/>	0	0	0.0
<input type="checkbox"/>	0	0	0.0
- Graph:** A line graph showing a linear relationship between x and y. The x-axis ranges from 0 to 5000, and the y-axis ranges from -0.0 to 10.0. A red line passes through the points (1000, 0) and (5000, 10). A '2' callout points to the 'Compute Curve' button above the graph.
- Form Fields:** Below the graph, there are input fields for 'Sensor name' (containing 'Fuel level') and 'Sensor type' (containing 'Volume'). A '3' callout points to the 'Save sensor' button.
- Buttons:** At the bottom right, there are buttons for 'Exit' (with a '4' callout), 'Delete sensor', 'Import sensors', 'Export selected sensor', and 'Export all sensor'.

Race Studio 2

To load the sensor in AiM device configuration:

- press "Device configuration" on the software left keyboard, select your device and the configuration where to load the sensor
- enable "Channels" layer (1)
- select the channel where to set the sensor on and select it from the drop down menu in "Sensor type" column (2)
- transmit the configuration to the device pressing "Transmit" (3)

